

Work Order ID 52147

Thursday, September 17, 2009 8:09:36 AM

Page 1

Item ID: D209-669-014

Accept

Revision ID: B

Item Name: Skidtube RH

Start Date: 9/18/2009 Start Qty: 1.00

Required Date: 10/9/2009 Req'd Qty: 1.00

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

QC:

Date:

SPC (Y/N):

Date:

Run

Start

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursDraw
NumberDraw
Rev.Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D209-669-014

Rev B

DSI 9450

Rev A

100

0.00



DC

Document Control

DOCUMENT CONTROL

Memo

0.00

Photocopy bluefile & type labels per PPP D209-669-014 CHG003

S 07/01/02

110

0.00



Packaging

Packaging

Pick Kit

Memo

0.00

9/09/09/30 ①

Work Order ID 52147

Thursday, September 17, 2009 8:09:36 AM

Page 2

Item ID: D209-669-014

Accept

Revision ID: B

Item Name: Skidtube RH

Start Date: 9/18/2009 Start Qty: 1.00

Required Date: 10/9/2009 Req'd Qty: 1.00

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

130

Packaging

0.00



Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPPD209-669-014
Location: _____

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control



Setup Start

Stop

Cust Item ID:

Customer:

⑩	4	_____	_____
---	---	-------	-------

_____ 9/18/02 ①

09/10/05 ⑧

09-10-2

Picklist Print

Thursday, September 17, 2009 8:09:35 AM

Page 1

Work Order ID: 52147

Parent Item: D209-669-014RevB

Parent Item Name: Skidtube RH

Comments:

Start Date: 9/18/2009

Required Date: 10/9/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

D209-669-043RevB

Manufactured

No

110

Each

3.0000

1.0000



Replacement Skidtube

52147 9/10/254

Warehouse

Loc Qty

Loc Code

Location

Premier

Mezz

3

22797

1

39205

1

39206

1

D2917-2RevB

Manufactured

No

110

Each

3.0000

2.0000



Saddle RH

8/30/09/30

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

FG

3

51328

3

D2918-2RevB

Manufactured

No

110

Each

3.0000

2.0000



Saddle RH

B521281x 9/10/01
8/30/09/30

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

3

43138

1

51330

2

B52132

1x

Picklist Print

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147

Parent Item: D209-669-014RevB

Parent Item Name: Skidtube RH

Comments:

Start Date: 9/18/2009

Required Date: 10/9/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

AN4-51A		Purchased	No			110	Each	354.0000	68.0000			
---------	--	-----------	----	--	--	-----	------	----------	---------	--	--	--

Bolt

Warehouse
Location

Loc Qty

Loc Code

Main Warehouse

ST	354	
110328	2	
111635	102	
112314	100	
112489	100	
112641	50	

9/30/09/30

D2570RevB		Manufactured	No			110	Each	139.0000	24.0000			
-----------	--	--------------	----	--	--	-----	------	----------	---------	--	--	--

Bushing

Warehouse
Location

Loc Qty

Loc Code

Main Warehouse

ST	15	
47246	15	
Main Warehouse		
ST36	124	
50356	124	

9/30/09/30

351519

24P

Picklist Print

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147

Parent Item: D209-669-014RevB

Parent Item Name: Skidtube RH



Comments:

Start Date: 9/18/2009

Required Date: 10/9/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
5 MS21042L4  Nut		Purchased	No			110	Each	8,148.000 / 24.0000			9/30/09	

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST	8148	
107499	5	
108145	4	
110450	1	
110507	184	
111827	5996	
112314	1893	24
15924	0	
7690	24	
8182	41	

8 AN5-36A

Bolt

Purchased No

110 Each 555.0000 / 4.0000



9/30/09

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST	555	
109545	11	
110467	7	
110731	4	
112243	20	
112314	463	4
112385	50	

Picklist Print

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147



Parent Item: D209-669-014RevB



Parent Item Name: Skidtube RH

Start Date: 9/18/2009

Required Date: 10/9/2009

Comments:

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

AN960JD516

Purchased

No

110

Each

1,097.000

8.0000



Washer

Warehouse

Loc Qty

Loc Code

Location

M112794

⑧

9/30/09/30

Main Warehouse

ST

1097

100564

2

106167

6

107534

34

107959

43

108246

46

108672

2

109059

49

109752

22

110363

46

110523

57

111279

43

112082

247

112314

500

MS21042L5

Purchased

No

110

Each

1,279.000

4.0000



Nut

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

1279

110382

10

111636

269

112314

1000

9/30/09/30

4

Thursday, September 17, 2009 8:09:35 AM

Shop Packet Print

Picklist Print

Page 5

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147



Parent Item: D209-669-014RevB



Parent Item Name: Skidtube RH


Start Date: 9/18/2009

Required Date: 10/9/2009

Comments:

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN4-7A  Bolt		Purchased	No			110	Each	201.0000	.16.0000			

9/20/09/30

<u>Warehouse</u>	<u>Loc Qty</u>	<u>Loc Code</u>
<u>Location</u>		
Main Warehouse		
ST	201	
111668	1	
112314	50	
112385	50	
112641	100	

1

15

Picklist Print

Page 6

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147

Parent Item: D209-669-014RevB

Parent Item Name: Skidtube RH



Comments:

Start Date: 9/18/2009

Required Date: 10/9/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN960JD416  Washer		Purchased	No			110	Each	8,313.000	32.0000		 09/09/30	

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST	8313	
102929	2	
105906	4	
106277	2	
107321	23	
107939	114	
108161	553	
108827	31	
109249	69	
110523	340	
111279	101	
111916	2187	32
112314	4887	
16941	0	

D2929RevB



Spacer

Manufactured No

110 Each 15.0000 2.0000



09/09/30

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST	15	
43376	15	2

Thursday, September 17, 2009 8:09:35 AM

Shop Packet Print

Page 6

Picklist Print

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147



Parent Item: D209-669-014RevB



Parent Item Name: Skidtube RH

Start Date: 9/18/2009

Required Date: 10/9/2009

Comments:

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

D2930RevB Manufactured No



Spacer

110

Each

11.0000

2.0000



9/30/09/30

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

11

43378

11

D3405-041RevB Manufactured No



Lug Assembly

110

Each

10.0000

1.0000



9/30/09/30

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

10

51254

10

B51673 (1X)

AN4C47A Purchased No



Bolt

110

Each

222.0000

4.0000



9/30/09/30

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

222

110847

4

112431

18

112489

100

112641

100

4

Picklist Print

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147



Parent Item: D209-669-014RevB



Parent Item Name: Skidtube RH

Start Date: 9/18/2009

Required Date: 10/9/2009

Comments:

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

MS21043-4		Purchased	No			110	Each	1,397.000	5.0000			
<div style="display: flex; justify-content: space-between;"> <div style="text-align: right;"> <p><i>Ep 09/09/30</i></p> </div> </div>												

Nut

<u>Warehouse</u>	<u>Loc Qty</u>	<u>Loc Code</u>
<u>Location</u>		
OFFSHORE		
FG	40	
104603	40	
Main Warehouse		
ST	1357	
111819	35	
112243	22	
112314	1000	
112492	300	

D3405-043RevB

Manufactured

No

110

Each

12.0000

1.0000



Lug Assembly

<u>Warehouse</u>	<u>Loc Qty</u>	<u>Loc Code</u>
<u>Location</u>		
Main Warehouse		
ST	12	
46589	1	
46863	1	
51255	10	

B51652

(1x)

Ep 09/09/30

Picklist Print

Page 9

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147



Parent Item: D209-669-014RevB



Parent Item Name: Skidtube RH

Start Date: 9/18/2009

Required Date: 10/9/2009

Comments:

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

D3407-041RevE Manufactured No

110

Each

35.0000

1.0000



Tow Ring

Warehouse
Location

Loc Qty

Loc Code

OFFSHORE

FG

3

35780

3

Main Warehouse

ST

1

48356

1

Main Warehouse

ST464

31

51659

31

D3456-1RevA

Manufactured No

110

Each

232.0000

1.0000



Washer

Warehouse
Location

Loc Qty

Loc Code

OFFSHORE

FG

7

25701

7

Main Warehouse

ST

225

46752

25

51653

200

Thursday, September 17, 2009 8:09:35 AM

Shop Packet Print

Page 9

Picklist Print

Page 10

Thursday, September 17, 2009 8:09:35 AM

Work Order ID: 52147



Parent Item: D209-669-014RevB



Parent Item Name: Skidtube RH

Start Date: 9/18/2009

Required Date: 10/9/2009

Comments:

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

S D3417-5RevE

Manufactured

No

110

Each

152.0000

2.0000



9/30/09/30

Washer

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

ST

152

51649

152

1

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D209-669 REV. B

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 32147

INSTRUCTIONS:

1) FOR D209-669-011/-012/-013/-014 SKID TUBES @ CHANGE 003 AND SUBSEQUENT, MODIFY THE FOLLOWING:

- a) REPLACE THE D2968-041 TOW RING WITH THE D3407-041 TOW RING ASSEMBLY.
- b) REPLACE THE D2736-1 AND D2736-3 GHW LUGS WITH THE D3405-041 AND D3405-043 LUG ASSEMBLIES.
- c) AMEND THE PARTS LIST IN SECTION 5.0 OF INSTALLATION INSTRUCTIONS IIN-D209-669 REV. B AS SHOWN ON PAGE 2 OF THIS DSI.

NOTE: ALL INSTALLATION FASTENERS FOR THE ABOVE CHANGES HAVE BEEN UPDATED. SEE THE AMENDED PARTS LIST ON PAGE 2 FOR DETAILS.

A	NEW ISSUE	AJS	09.02.24
REV.	DESCRIPTION	BY	DATE
DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9450	SHEET 1 OF 3
APPROVED		TITLE	SCALE
DE APPR.		SKIDTUBE INSTALLATIONS	NTS
DATE	09.02.24	COPYRIGHT © 2009 BY DART AEROSPACE LTD <small>THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR REPRODUCED IN ANY MANNER WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD</small>	

5.0 PARTS LIST

52147

ITEM	QTY -011	QTY -012	QTY -013	QTY -014	QTY -041	QTY -043	PART NUMBER	DESCRIPTION
	X						D209-669-011	SKIDTUBE INSTALLATION, LH (AH-1W/J)
		X					D209-669-012	SKIDTUBE INSTALLATION, RH (AH-1W/J)
			X				D209-669-013	SKIDTUBE INSTALLATION, LH (AH-1P/F/S)
				X			D209-669-014	SKIDTUBE INSTALLATION, RH (AH-1P/F/S)
	1	1			X		D209-669-041	REPLACEMENT SKIDTUBE (AH-1W/J)
			1	1		X	D209-669-043	REPLACEMENT SKIDTUBE (AH-1P/F/S)

IS:

50	4	4	1	1			D3405-041	LUG ASSEMBLY
51	8	8	4	4			AN4C47A	BOLT
52	16	16	8	8			D2570	BUSHING
53	8	8	4	4			MS21043-4	NUT
54			1	1			D3405-043	LUG ASSEMBLY
60	1	1	1	1			D3407-041	TOW RING ASSEMBLY
61	1	1	1	1			D3456-1	WASHER
62	1	1	1	1			MS21043-4	NUT
63	2	2	2	2			D3417-5	WASHER

WAS:


50	4	4	1	1			D2736-1	GHW LUG
51	8	8	4	4			AN4-46A	BOLT
52	16	16	8	8			D2570	BUSHING
53	8	8	4	4			MS21042L4	NUT (OR MS21042-4)
54			1	1			D2736-3	GHW LUG
60	1	1	1	1			D2968-041	TOW RING
61	1	1	1	1			AN970-4	WASHER
62	1	1	1	1			MS21042L4	NUT (OR MS21042-4)

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9450	SHEET 2 OF 3
APPROVED		TITLE	SCALE
DE APPR.		SKIDTUBE INSTALLATIONS	NTS
DATE	09.02.24	COPYRIGHT © 2009 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT THE WRITTEN PERMISSION FROM DART AEROSPACE LTD.	


52147

INSTALL TOW RING ASSEMBLY AS SHOWN BELOW (REFER TO SECTION F-F OF IIN-D209-669 REV. B.

IS:



WAS:



NO PICTORIAL CHANGE REQUIRED FOR GROUND HANDLING WHEEL LUG CHANGES.

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9450	SHEET 3 OF 3
APPROVED		TITLE	SCALE
DE APPR.		SKIDTUBE INSTALLATIONS	NTS
DATE	09.02.24	COPYRIGHT © 2009 BY DART AEROSPACE LTD <small>THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD</small>	

4.0 WEIGHT AND BALANCE

The following weight and balance information is for the replacement Dart parts. The weight and balance of the skidtubes that are being removed from the aircraft is the responsibility of the installer.

Installation	Weight	LONGITUDINAL	
		Arm	Moment
D209-669-011/-012 SKIDTUBE INSTALLATION	49.6 lb 22.5 kg	170.4 in 4.33 m	8452 in lb 97.4 m kg
D209-669-013/-014 SKIDTUBE INSTALLATION	43.8 lb 19.9 kg	176.5 in 4.48 m	7731 in lb 89.2 m kg

REFERENCE ONLY

5.0 PARTS LIST

Item	Qty -011	Qty -012	Qty -013	Qty -014	Qty -041	Qty -043	Part Number	Description
	X						D209-669-011	SKIDTUBE INSTALLATION, LH (AH-1W/J)
		X					D209-669-012	SKIDTUBE INSTALLATION, RH (AH-1W/J)
			X				D209-669-013	SKIDTUBE INSTALLATION, LH (AH-1P/F/S)
				X			D209-669-014	SKIDTUBE INSTALLATION, RH (AH-1P/F/S)
	1	1			X		D209-669-041	REPLACEMENT SKIDTUBE (AH-1W/J)
			1	1		X	D209-669-043	REPLACEMENT SKIDTUBE (AH-1P/F/S)
1A					1		D2906-041	SKIDTUBE ASSEMBLY
1B						1	D2906-043	SKIDTUBE ASSEMBLY
2	1		2				D2917-1	OUTER SADDLE (FWD, LH)
3		1		2			D2917-2	OUTER SADDLE (FWD, RH)
4	1		2				D2918-1	INNER SADDLE (FWD, LH)
5		1		2			D2918-2	INNER SADDLE (FWD, RH)
6	1						D2919-1	OUTER SADDLE (AFT, LH)
7		1					D2919-2	OUTER SADDLE (AFT, RH)
8	1						D2920-1	INNER SADDLE (AFT, LH)
9		1					D2920-2	INNER SADDLE (AFT, RH)
10	8	8	8	8			AN4-51A	BOLT
11	16	16	16	16			D2570	BUSHINGS
12	8	8	8	8			MS21042L4	NUT (OR MS21042-4)
13	2	2	4	4			AN5-36A	BOLT
14	2	2					AN5-41A	BOLT
15	8	8	8	8			AN960JD516	WASHER
16	4	4	4	4			MS21042L5	NUT (OR MS21042-5)
17	16	16	16	16			AN4-7A	BOLT
18	32	32	32	32			AN960JD416	WASHER
19	16	16	16	16			MS21042L4	NUT (OR MS21042-4)

CONTINUED ON NEXT PAGE

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: B
Date: 07.08.23

52147

CONTINUED FROM PREVIOUS PAGE

20	2	2	2	2			D2929	SPACER
21	2	2	2	2			D2930	SPACER
*30A					1	1	D3564-9	WEARSHOE (REPLACES D2577-1)
*30B					1	1	D3566-1	GASKET
*31A					1		D3564-15	WEARSHOE (REPLACES 18" D2577-5)
*31B					1		D3566-15	GASKET
*32A					1	1	D3564-11	WEARSHOE (REPLACES D2577-3)
*32B					1	1	D3566-1	GASKET
*33A					1	1	D3564-5	WEARSHOE (REPLACES D2577-5)
*33B					1	1	D3566-5	GASKET
*34					50	44	AN3C4A	BOLT (REPLACES AN3-4A)
*35					50	44	AN960C10L	WASHER (REPLACES AN960JD10L)
*36					50	44	AKS7-1032-130	INSERT (OR ALS7-1032-130, OR ALS4-1032-130, OR AKS4-1032-130)
*37					12	14	D2594-1	PLUG
*38					12	14	D2594-3	O-RING
*40					2	2	D2855	AFT CAP
*41					4	4	AN3-5A	BOLT
*42					4	4	AN960JD10L	WASHER
*43					4	4	AKS7-1032-225	INSERT (OR ALS7-1032-225, OR ALS4-1032-225, OR AKS4-1032-225)
50	4	4	1	1			D2736-1	GHW LUG
51	8	8	4	4			AN4-46A	BOLT
52	16	16	8	8			D2570	BUSHING
53	8	8	4	4			MS21042L4	NUT (OR MS21042-4)
54			1	1			D2736-3	LUG ASSEMBLY
60	1	1	1	1			D2968-041	TOW RING
61	1	1	1	1			AN970-4	WASHER
62	1	1	1	1			MS21042L4	NUT (OR MS21042-4)

* DENOTES THAT PART IS INCLUDED WITH D2906-041/-043 SKIDTUBE ASSEMBLY

52146